

## ASCOM IP-DECT CERTIFIED IP PBX PLATFORMS

	IP PBX MODEL(S)	IP PBX SW VERSION(S)	ASCOM IP-DECT SW VERSION(S)
<b>Aastra</b>	Ascotel	i7.6 (7648g1)	2.3.7
<b>Aastra</b>	Aastra AXS R5.1, A5000 R5.2 (France Only)	R5.1 & R5.2	3.4.12
<b>Aastra</b>	Aastra MX-ONE	4.1 SP1 (Hotfix 1)	4.1.24
<b>Advoco</b>	Advoco NetPBX 5.1 & Acme Packet SBC 6.10 (Arcstel)	5.1 & 6.10	4.1.31
<b>Alcatel-Lucent</b>	Alcatel-Lucent OXE	R10 (J1.401.34c)	4.1.33
<b>Alcatel-Lucent</b>	Alcatel-Lucent OXE	R10 (J1.501.11c)	5.1.8
<b>Alcatel-Lucent</b>	Alcatel-Lucent OXE	R11 (K1.400.25e)	6.1.3
<b>Alcatel-Lucent</b>	Alcatel-Lucent OXE	R11 (K1.400.30f)	7.0.5
<b>Alcatel-Lucent</b>	Alcatel-Lucent OXE	R11.1 (I1.301.17f))	7.2.7
<b>Alcatel-Lucent</b>	Alcatel-Lucent OXE	R11.2 (I2.300.31b)	9.0.6
<b>Alcatel-Lucent</b>	Alcatel-Lucent OXE	R12 (m1.401.12.d)	9.1.11
<b>Alcatel-Lucent</b>	Alcatel-Lucent OXE	R12 (m1.403.16.a)	10.0.6
<b>Alcatel-Lucent</b>	Alcatel-Lucent OXE	R12.4 (M5.204)	11.1.5
<b>Alcatel-Lucent</b>	Alcatel-Lucent OXO	R920 (035.002)	7.0.5
<b>Alcatel-Lucent</b>	Alcatel-Lucent OXO	R10.0 (R100.036.001)	7.2.7
<b>Alcatel-Lucent</b>	Alcatel-Lucent OXO Connect	R3.1	10.3.5
<b>Alcatel-Lucent</b>	Alcatel-Lucent OXO Connect	R4.0	11.4.4

	IP PBX MODEL(S)	IP PBX SW VERSION(S)	ASCOM IP-DECT SW VERSION(S)
<b>Audiocodes</b>	Audiocodes SPS (for MS Lync)	2.43	5.1.8
<b>Audiocodes</b>	Audiocodes SPS (for MS Lync and Skype for Business)	3.0.41	9.1.11
<b>AVAYA</b>	Avaya Aura™ Communication Manager Branch	2.0.0_28.01	3.2.2
<b>AVAYA</b>	Avaya S8300 Server running Avaya Aura™ Communication Manager	5.2	3.2.2
<b>AVAYA</b>	Avaya Aura Communication Manager Avaya Aura Session Manager	R016x.00.1.510.1 Patch: 00.1.510.1-18857 6.1.0.0.610023	4.1.37
<b>AVAYA</b>	Avaya Aura Communication Manager Avaya Aura Session Manager	R6.2 SP4 (R016x.02.0.823.0) R6.2 SP3 (6.2.3.0.623006)	5.1.2
<b>AVAYA</b>	Avaya Aura Communication Manager Avaya Aura Session Manager	R6.3 SP1 (R016x.03.0.124.0) R6.3 SP3 (6.3.3.0.633004)	7.0.1
<b>AVAYA</b>	Avaya Aura Communication Manager Avaya Aura Session Manager	R7.0 R7.0	8.0.8
<b>AVAYA</b>	Avaya Aura Communication Manager Avaya Aura Session Manager	R7.1 R7.1	10.1.4
<b>AVAYA</b>	Avaya Aura Communication Manager Avaya Aura Session Manager	R8.0.1 R8.0.1	10.3.5
<b>AVAYA</b>	Avaya Aura Communication Manager Avaya Aura Session Manager	R8.1 R8.1	11.3.4
<b>AVAYA</b>	Avaya Aura Communication Manager Avaya Aura Session Manager	R10.1 R10.1	11.7.2
<b>AVAYA</b>	Avaya IP Office (IP500) Avaya IP Office Manager	6.0 (8) 8.0 (8)	3.4.12
<b>AVAYA</b>	Avaya IP Office (IP500) Avaya IP Office Manager	7.0 (5) 9.0 (5)	4.1.33
<b>AVAYA</b>	Avaya IP Office (IP500) Avaya IP Office Manager	9.0 (Build 829) 9.0 (Build 829)	7.0.1
<b>AVAYA</b>	Avaya IP Office (Server & IP500)	10.0 (Build 550)	9.0.6

	IP PBX MODEL(S)	IP PBX SW VERSION(S)	ASCOM IP-DECT SW VERSION(S)
<b>AVAYA</b>	Avaya IP Office (Server & IP500)	11.0 (Build 8)	10.2.9
<b>AVAYA</b>	Avaya IP Office (Server & IP500)	11.1 (Build 209)	11.3.4
<b>AVAYA</b>	Avaya Communication Server 1000	Release 7.5	4.1.37
<b>AVAYA</b>	Avaya Communication Server 1000	Release 7.6	7.1.4
<b>AVAYA</b>	Avaya Communication Server 1000	Release 7.65 (SP9)	10.1.4
<b>Broadsoft</b>	Broadsoft BroadWorks	19 SP1	6.1.2
<b>Cisco (formerly Broadsoft)</b>	Cisco BroadWorks	Release 23.0	11.1.5
<b>Cisco</b>	Cisco Unified Communications Manager	6.1.1.2000-3	2.3.5
<b>Cisco</b>	Cisco Unified Communications Manager	7.1.3.30000-1	3.2.6
<b>Cisco</b>	Cisco Unified Communications Manager	8.6.1.20000-1	5.0.11
<b>Cisco</b>	Cisco Unified Communications Manager	8.6.1.20000-1	5.1
<b>Cisco</b>	Cisco Unified Communications Manager	9.1.1.10000-11	6.1
<b>Cisco</b>	Cisco Unified Communications Manager	10.0.1.10000-24	7.2.7
<b>Cisco</b>	Cisco Unified Communications Manager	11.0.1.10000-10	8.0.9
<b>Cisco</b>	Cisco Unified Communications Manager	12.0	10.0.6
<b>Cisco</b>	Cisco Unified Communications Manager	14.0	11.4.4
<b>Innovaphone</b>	Innovaphone IP302, IP800, IP6000	8.00 (hotfix5)	3.4.12
<b>Innovaphone</b>	Innovaphone IP302, IP800, IP6000	9.00 final	4.1.33

	IP PBX MODEL(S)	IP PBX SW VERSION(S)	ASCOM IP-DECT SW VERSION(S)
<b>Innovaphone</b>	Innovaphone IP302, IP800, IP6000	9.00 (hotfix15)	5.1.12
<b>Innovaphone</b>	Innovaphone IP302, IP800, IP810, IP6000, IP6010	10.00	6.1.3
<b>Innovaphone</b>	Innovaphone IP302, IP800, IP810, IP6000, IP6010	11r2	9.0.6
<b>Innovaphone</b>	Innovaphone IP302, IP800, IP810, IP6000, IP6010	12r1	9.0.6
<b>Innovaphone</b>	Innovaphone IP810, IP6010, IPVA	13r1	11.1.5
<b>Innovaphone</b>	Innovaphone FXO IP38	10.00	7.0.5
<b>Mitel</b>	Mitel MiVoice Business (MCD 3300)	6.0 SP1	6.1.3
<b>Mitel</b>	Mitel MiVoice Business (MCD 3300)	7.0 SP1	7.2.7
<b>Mitel</b>	Mitel MiVoice Office (5000)	6.0 SP1	7.0.5
<b>Mitel</b>	Mitel MiVoice MX-One	6.0 SP2 and 6.1	8.0.9
<b>ShoreTel</b>	ShoreTel	R8.1 (build 13.23.6912.0)	3.0.52
<b>ShoreTel</b>	ShoreTel	R9.2	3.0.52
<b>ShoreTel</b>	ShoreTel	R10	3.0.52
<b>ShoreTel</b>	ShoreTel	R12.1	5.0.7
<b>ShoreTel</b>	ShoreTel	R13.2	6.1.2
<b>ShoreTel</b>	ShoreTel	R14.2	7.1.3
<b>ShoreTel</b>	ShoreTel Connect	21.79.9330.0	9.0.6
<b>Unify</b>	OpenScape Voice	V8	8.0.8
<b>Unify</b>	OpenScape Voice	V9	9.1.11
<b>Unify</b>	OpenScape Voice	V9	10.2.9
<b>Unify</b>	OpenScape Voice	V10	11.3.4
<b>Unify</b>	OpenScape Business	V3	11.1.6
<b>Unify</b>	OpenScape 4K	V7	8.0.8

	IP PBX MODEL(S)	IP PBX SW VERSION(S)	ASCOM IP-DECT SW VERSION(S)
Unify	OpenScape 4K	V8	9.1.11
Unify	OpenScape 4K	V8	10.2.9
Unify	OpenScape 4K	V10	11.1.6

Ascom supports only IP-PBX Infrastructures listed in this document. The table above should be used in conjunction with the information published on Ascom's interoperability webpage: <https://www.ascom-ws.com/AscomPartnerWeb/en/startpage/Sales-tools/Interoperability/> (login required).

Effective July 15<sup>th</sup>, 2022. The most recent version can be found on the interoperability webpage.  
For questions contact [interop@ascom.com](mailto:interop@ascom.com).